

Unique Property Ref No.	Area	Flat	Address	Survey Date	Assessor's Name	Room Name	Room No.	Item Ref. No.	Lab Ref. number	Photo Reference	CAD Reference	Location of Asbestos/Comments	Product Type	Damage	Surface Treatment	Asbestos Type	Normal Occupant Activity	Likelihood of Disturbance	Human Exposure Potential	Maintenance Activity	Total Priority Score	Quantity	Identification Type	Recommendation	Re-Inspection Date
A22	Charmouth	4-10	Ellesdon	Oct-10	OP/MB	Main Bui	EX.01	-	As 2, Bldg 3-9 Ellesdon	-	A22.1	Felt to roof.	0	0	0	NAD	0	0	0	0	0	100m2	SP	None	None
A22	Charmouth	4-10	Ellesdon	Oct-10	OP/MB	Main Bui	EX.01	-	As 1, Bldg 3-9 Ellesdon	-	A22.1	Damp proof course to building.	1	1	0	1	0	2	0	0	2	60 LM	SP	MM	
A22	Charmouth	4-10	Ellesdon	Oct-10	OP/MB	Main Bui	EX.01	-	Vis ID	A22.1	A22.1	Asbestos cement soil pipes & hoppers x4.	1	0	0	1	0	2	0	0	2	12 LM	SP	MM	
A22	Charmouth	4-10	Ellesdon	Oct-10	OP/MB	Main Bui	EX.01	-	Vis ID	-	A22.1	Asbestos cement chimney cowl.	1	0	1	1	0	2	0	0	2	60 LM	SP	MM	
A22	Charmouth	4-10	Ellesdon	Oct-10	OP/MB	Main Bui	EX.01					Brick walls. Concrete roof tiles. Concrete flintlock guttering (lined with aluminium). Concrete verge undercloaking. Plastic rainwater pipes. Concrete tile window sills.													
A22	Charmouth	4-10	Ellesdon	Oct-10	OP/MB	Porch	EX.02	-	As 2, Bldg 3-9 Ellesdon	-	A22.1	Roof felt under tiles to porch roof.	0	0	0	NAD	0	0	0	0	0	4m2	SP	None	None
A22	Charmouth	4-10	Ellesdon	Oct-10	OP/MB	Porch	EX.02					Brick walls, Concrete roof tiles & concrete roof tile as verge undercloaking. Plastic fascia & soffits. Hardboard to internal soffit.													
A22	Charmouth	4-10	Ellesdon	Oct-10	OP/MB	Stairwell	G.01					Solid walls. Concrete floor, stairs & skirting. Concrete ceiling to ground floor. Plasterboard ceiling to 1st floor. Timber doors & frames.													
A23	Charmouth	11-17	Bridge Road	Oct-10	OP/MB	Main Bui	EX.01	-	As 1 Bldg 23-29		A23.1	Felt to main roof.	0	0	0	NAD	0	0	0	0	0	200m2	SP	None	None
A23	Charmouth	11-17	Bridge Road	Oct-10	OP/MB	Main Bui	EX.01	-	As 2 Bldg 23-29	A23.1	A23.1	Damp proof course to main building, porch & sheds.	1	1	0	1	0	1	1	0	2	60 LM	SP	MM	
A23	Charmouth	11-17	Bridge Road	Oct-10	OP/MB	Main Bui	EX.01	-	Vis ID	A23.2	A23.1	Asbestos cement chimney cowl.	1	0	1	1	0	0	0	0	0	x6	SP	MM	
A23	Charmouth	11-17	Bridge Road	Oct-10	OP/MB	Main Bui	EX.01					Brick walls. Concrete tile roof & verge undercloaking. Concrete flint lock guttering. Plastic downpipes. Plain tile window sill.													
A23	Charmouth	11-17	Bridge Road	Oct-10	OP/MB	Porch	EX.02	-	As 1 Bldg 23-29	-	A23.1	Felt to porch roof.	0	0	0	0	0	0	0	0	0	5m2	SP	None	None
A23	Charmouth	11-17	Bridge Road	Oct-10	OP/MB	Porch	EX.02	-	Vis ID	A23.3	A23.1	Asbestos cement soffits & inside porch ceiling soffit.	1	0	1	1	0	1	0	0	1	Unknown	SP	MM	
A23	Charmouth	11-17	Bridge Road	Oct-10	OP/MB	Porch	EX.02					Brick walls. Plain tile roof & verge. Lead flash to porch.													
A23	Charmouth	11-17	Bridge Road	Oct-10	OP/MB	Sheds	EX.03	-	As 2 Bldg 23-29		A23.1	Damp proof course.	1	1	0	1	0	1	1	0	2	15 LM	SP	MM	

